



# Upínač Weldon pro upínací stopky

## Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B





| Název             | Kužel | D  | d  | A   |  | G 2,5<br>25.000 min <sup>-1</sup> |
|-------------------|-------|----|----|-----|---|-----------------------------------|
| SK40.50.WE.06.AD  | SK40  | 25 | 6  | 50  | AD  | •                                 |
| SK40.50.WE.08.AD  | SK40  | 28 | 8  | 50  | AD  | •                                 |
| SK40.50.WE.10.AD  | SK40  | 35 | 10 | 50  | AD  | •                                 |
| SK40.50.WE.12.AD  | SK40  | 42 | 12 | 50  | AD  | •                                 |
| SK40.50.WE.14.AD  | SK40  | 44 | 14 | 50  | AD  | •                                 |
| SK40.63.WE.16.AD  | SK40  | 48 | 16 | 63  | AD  | •                                 |
| SK40.63.WE.18.AD  | SK40  | 50 | 18 | 63  | AD  | •                                 |
| SK40.63.WE.20.AD  | SK40  | 52 | 20 | 63  | AD  | •                                 |
| SK40.100.WE.25.AD | SK40  | 65 | 25 | 100 | AD  | •                                 |
| SK40.100.WE.32.AD | SK40  | 72 | 32 | 100 | AD  | •                                 |
| SK40.100.WE.06.AD | SK40  | 25 | 6  | 100 | AD  | •                                 |
| SK40.100.WE.08.AD | SK40  | 28 | 8  | 100 | AD  | •                                 |
| SK40.100.WE.10.AD | SK40  | 35 | 10 | 100 | AD  | •                                 |
| SK40.100.WE.12.AD | SK40  | 42 | 12 | 100 | AD  | •                                 |
| SK40.100.WE.14.AD | SK40  | 44 | 14 | 100 | AD  | •                                 |
| SK40.100.WE.16.AD | SK40  | 48 | 16 | 100 | AD  | •                                 |
| SK40.100.WE.18.AD | SK40  | 50 | 18 | 100 | AD  | •                                 |
| SK40.100.WE.20.AD | SK40  | 52 | 20 | 100 | AD  | •                                 |

od průměr d = 25 se dvěma upínacími šrouby

# Upínač Weldon pro upínací stopky

## Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B





| Název              | Kužel | D  | d  | A   |  | G 2,5<br>25.000 min <sup>-1</sup> |
|--------------------|-------|----|----|-----|---|-----------------------------------|
| SK40.35.WE.16.ADB  | SK40  | 45 | 16 | 35  | AD/B  | •                                 |
| SK40.35.WE.20.ADB  | SK40  | 45 | 20 | 35  | AD/B  | •                                 |
| SK40.35.WE.25.ADB  | SK40  | 45 | 25 | 35  | AD/B  | •                                 |
| SK40.65.WE.32.ADB  | SK40  | 50 | 32 | 65  | AD/B  | •                                 |
| SK40.50.WE.06.ADB  | SK40  | 25 | 6  | 50  | AD/B  | •                                 |
| SK40.50.WE.08.ADB  | SK40  | 28 | 8  | 50  | AD/B  | •                                 |
| SK40.50.WE.10.ADB  | SK40  | 35 | 10 | 50  | AD/B  | •                                 |
| SK40.50.WE.12.ADB  | SK40  | 42 | 12 | 50  | AD/B  | •                                 |
| SK40.50.WE.14.ADB  | SK40  | 44 | 14 | 50  | AD/B  | •                                 |
| SK40.63.WE.16.ADB  | SK40  | 48 | 16 | 63  | AD/B  | •                                 |
| SK40.63.WE.18.ADB  | SK40  | 50 | 18 | 63  | AD/B  | •                                 |
| SK40.63.WE.20.ADB  | SK40  | 52 | 20 | 63  | AD/B  | •                                 |
| SK40.100.WE.25.ADB | SK40  | 65 | 25 | 100 | AD/B  | •                                 |
| SK40.100.WE.32.ADB | SK40  | 72 | 32 | 100 | AD/B  | •                                 |
| SK40.120.WE.40.ADB | SK40  | 80 | 40 | 120 | AD/B  | •                                 |
| SK40.100.WE.06.ADB | SK40  | 25 | 6  | 100 | AD/B  | •                                 |
| SK40.100.WE.08.ADB | SK40  | 28 | 8  | 100 | AD/B  | •                                 |
| SK40.100.WE.10.ADB | SK40  | 35 | 10 | 100 | AD/B  | •                                 |
| SK40.100.WE.12.ADB | SK40  | 42 | 12 | 100 | AD/B  | •                                 |
| SK40.100.WE.14.ADB | SK40  | 44 | 14 | 100 | AD/B  | •                                 |
| SK40.100.WE.16.ADB | SK40  | 48 | 16 | 100 | AD/B  | •                                 |
| SK40.100.WE.18.ADB | SK40  | 50 | 18 | 100 | AD/B  | •                                 |
| SK40.100.WE.20.ADB | SK40  | 52 | 20 | 100 | AD/B  | •                                 |
| SK40.130.WE.06.ADB | SK40  | 25 | 6  | 130 | AD/B  | •                                 |
| SK40.130.WE.08.ADB | SK40  | 28 | 8  | 130 | AD/B  | •                                 |
| SK40.130.WE.10.ADB | SK40  | 35 | 10 | 130 | AD/B  | •                                 |
| SK40.130.WE.12.ADB | SK40  | 42 | 12 | 130 | AD/B  | •                                 |
| SK40.130.WE.14.ADB | SK40  | 44 | 14 | 130 | AD/B  | •                                 |
| SK40.130.WE.16.ADB | SK40  | 48 | 16 | 130 | AD/B  | •                                 |
| SK40.130.WE.18.ADB | SK40  | 50 | 18 | 130 | AD/B  | •                                 |
| SK40.130.WE.20.ADB | SK40  | 52 | 20 | 130 | AD/B  | •                                 |
| SK40.160.WE.06.ADB | SK40  | 25 | 6  | 160 | AD/B  | •                                 |
| SK40.160.WE.08.ADB | SK40  | 28 | 8  | 160 | AD/B  | •                                 |
| SK40.160.WE.10.ADB | SK40  | 35 | 10 | 160 | AD/B  | •                                 |
| SK40.160.WE.12.ADB | SK40  | 42 | 12 | 160 | AD/B  | •                                 |
| SK40.160.WE.14.ADB | SK40  | 44 | 14 | 160 | AD/B  | •                                 |
| SK40.160.WE.16.ADB | SK40  | 48 | 16 | 160 | AD/B  | •                                 |
| SK40.160.WE.18.ADB | SK40  | 50 | 18 | 160 | AD/B  | •                                 |
| SK40.160.WE.20.ADB | SK40  | 52 | 20 | 160 | AD/B  | •                                 |
| SK40.160.WE.25.ADB | SK40  | 65 | 25 | 160 | AD/B  | •                                 |
| SK40.160.WE.32.ADB | SK40  | 72 | 32 | 160 | AD/B  | •                                 |
| SK40.160.WE.40.ADB | SK40  | 80 | 40 | 160 | AD/B  | •                                 |

od průměr d = 25 se dvěma upínacími šrouby

# Upínač Weldon pro upínací stopky

## Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B





| Název              | Kužel | D  | d  | A   |  | G 2,5<br>25.000 min <sup>-1</sup> |
|--------------------|-------|----|----|-----|---|-----------------------------------|
| SK50.63.WE.06.ADB  | SK50  | 25 | 6  | 63  | AD/B  | •                                 |
| SK50.63.WE.08.ADB  | SK50  | 28 | 8  | 63  | AD/B  | •                                 |
| SK50.63.WE.10.ADB  | SK50  | 35 | 10 | 63  | AD/B  | •                                 |
| SK50.63.WE.12.ADB  | SK50  | 42 | 12 | 63  | AD/B  | •                                 |
| SK50.63.WE.14.ADB  | SK50  | 44 | 14 | 63  | AD/B  | •                                 |
| SK50.63.WE.16.ADB  | SK50  | 48 | 16 | 63  | AD/B  | •                                 |
| SK50.63.WE.18.ADB  | SK50  | 50 | 18 | 63  | AD/B  | •                                 |
| SK50.63.WE.20.ADB  | SK50  | 52 | 20 | 63  | AD/B  | •                                 |
| SK50.80.WE.25.ADB  | SK50  | 65 | 25 | 80  | AD/B  | •                                 |
| SK50.100.WE.32.ADB | SK50  | 72 | 32 | 100 | AD/B  | •                                 |
| SK50.100.WE.40.ADB | SK50  | 80 | 40 | 100 | AD/B  | •                                 |
| SK50.120.WE.50.ADB | SK50  | 99 | 50 | 120 | AD/B  | •                                 |
| SK50.100.WE.06.ADB | SK50  | 25 | 6  | 100 | AD/B  | •                                 |
| SK50.100.WE.08.ADB | SK50  | 28 | 8  | 100 | AD/B  | •                                 |
| SK50.100.WE.10.ADB | SK50  | 35 | 10 | 100 | AD/B  | •                                 |
| SK50.100.WE.12.ADB | SK50  | 42 | 12 | 100 | AD/B  | •                                 |
| SK50.100.WE.14.ADB | SK50  | 44 | 14 | 100 | AD/B  | •                                 |
| SK50.100.WE.16.ADB | SK50  | 48 | 16 | 100 | AD/B  | •                                 |
| SK50.100.WE.18.ADB | SK50  | 50 | 18 | 100 | AD/B  | •                                 |
| SK50.100.WE.20.ADB | SK50  | 52 | 20 | 100 | AD/B  | •                                 |
| SK50.120.WE.25.ADB | SK50  | 65 | 25 | 120 | AD/B  | •                                 |
| SK50.130.WE.06.ADB | SK50  | 25 | 6  | 130 | AD/B  | •                                 |
| SK50.130.WE.08.ADB | SK50  | 28 | 8  | 130 | AD/B  | •                                 |
| SK50.130.WE.10.ADB | SK50  | 35 | 10 | 130 | AD/B  | •                                 |
| SK50.130.WE.12.ADB | SK50  | 42 | 12 | 130 | AD/B  | •                                 |
| SK50.130.WE.14.ADB | SK50  | 44 | 14 | 130 | AD/B  | •                                 |
| SK50.130.WE.16.ADB | SK50  | 48 | 16 | 130 | AD/B  | •                                 |
| SK50.130.WE.18.ADB | SK50  | 50 | 18 | 130 | AD/B  | •                                 |
| SK50.130.WE.20.ADB | SK50  | 52 | 20 | 130 | AD/B  | •                                 |

od průměr d = 25 se dvěma upínacími šrouby

# Upínač Weldon pro upínací stopky

## Upínač Weldon DIN 6359 pro upínací stopky DIN 1835-B



| Název              | Kužel | D  | d  | A   |  | G 2,5<br>25.000 min <sup>-1</sup> |
|--------------------|-------|----|----|-----|---|-----------------------------------|
| SK50.160.WE.06.ADB | SK50  | 25 | 6  | 160 | AD/B  | •                                 |
| SK50.160.WE.08.ADB | SK50  | 28 | 8  | 160 | AD/B  | •                                 |
| SK50.160.WE.10.ADB | SK50  | 35 | 10 | 160 | AD/B  | •                                 |
| SK50.160.WE.12.ADB | SK50  | 42 | 12 | 160 | AD/B  | •                                 |
| SK50.160.WE.14.ADB | SK50  | 44 | 14 | 160 | AD/B  | •                                 |
| SK50.160.WE.16.ADB | SK50  | 48 | 16 | 160 | AD/B  | •                                 |
| SK50.160.WE.18.ADB | SK50  | 50 | 18 | 160 | AD/B  | •                                 |
| SK50.160.WE.20.ADB | SK50  | 52 | 20 | 160 | AD/B  | •                                 |
| SK50.160.WE.25.ADB | SK50  | 65 | 25 | 160 | AD/B  | •                                 |
| SK50.160.WE.32.ADB | SK50  | 72 | 32 | 160 | AD/B  | •                                 |
| SK50.160.WE.40.ADB | SK50  | 80 | 40 | 160 | AD/B  | •                                 |
| SK50.200.WE.06.ADB | SK50  | 25 | 6  | 200 | AD/B  | •                                 |
| SK50.200.WE.08.ADB | SK50  | 28 | 8  | 200 | AD/B  | •                                 |
| SK50.200.WE.10.ADB | SK50  | 35 | 10 | 200 | AD/B  | •                                 |
| SK50.200.WE.12.ADB | SK50  | 42 | 12 | 200 | AD/B  | •                                 |
| SK50.200.WE.14.ADB | SK50  | 44 | 14 | 200 | AD/B  | •                                 |
| SK50.200.WE.16.ADB | SK50  | 48 | 16 | 200 | AD/B  | •                                 |
| SK50.200.WE.18.ADB | SK50  | 50 | 18 | 200 | AD/B  | •                                 |
| SK50.200.WE.20.ADB | SK50  | 52 | 20 | 200 | AD/B  | •                                 |
| SK50.200.WE.25.ADB | SK50  | 65 | 25 | 200 | AD/B  | •                                 |
| SK50.200.WE.32.ADB | SK50  | 72 | 32 | 200 | AD/B  | •                                 |
| SK50.200.WE.40.ADB | SK50  | 80 | 40 | 200 | AD/B  | •                                 |

od průměr d = 25 se dvěma upínacími šrouby