


Upínač pro nástroje s morse stopkou a závitem dle DIN228-A

DIN 228-1 Form A



Název	Kužel	MK	D	A	G 6,3 15.000 min ⁻¹
BT40.50.MKS.1	BT40	1	25	50	•
BT40.50.MKS.2	BT40	2	32	50	•
BT40.70.MKS.3	BT40	3	40	70	•
BT40.95.MKS.4	BT40	4	48	95	•
BT40.110.MKS.4.D*	BT40	4	63	110	•
BT50.45.MKS.1	BT50	1	25	45	•
BT50.60.MKS.2	BT50	2	32	60	•
BT50.65.MKS.3	BT50	3	40	65	•
BT50.70.MKS.4	BT50	4	48	70	•
BT50.85.MKS.4.D*	BT50	4	63	85	•
BT50.100.MKS.5	BT50	5	63	100	•
BT50.118.MKS.5.D*	BT50	5	78	118	•

* s upínací drážkou dle DIN 2201