


Upínač pro nástroje s Morse stopkou

a závitem dle DIN 228-1 Form A



| Název | Kužel | D | MK | A | G 6,3 15.000 min ⁻¹ |
|--------------------|-------|----|----|-----|-----------------------------------|
| ISO40.50.MKS.1 | ISO40 | 25 | 1 | 50 | • |
| ISO40.50.MKS.2 | ISO40 | 32 | 2 | 50 | • |
| ISO40.65.MKS.3 | ISO40 | 40 | 3 | 65 | • |
| ISO40.95.MKS.4 | ISO40 | 48 | 4 | 95 | • |
| ISO40.110.MKS.4.D* | ISO40 | 63 | 4 | 110 | • |
| ISO50.60.MKS.1 | ISO50 | 25 | 1 | 60 | • |
| ISO50.60.MKS.2 | ISO50 | 32 | 2 | 60 | • |
| ISO50.65.MKS.3 | ISO50 | 40 | 3 | 65 | • |
| ISO50.65.MKS.4 | ISO50 | 48 | 4 | 65 | • |
| ISO50.80.MKS.4.D* | ISO50 | 63 | 4 | 80 | • |
| ISO50.120.MKS.5 | ISO50 | 63 | 5 | 120 | • |
| ISO50.138.MKS.5.D* | ISO50 | 78 | 5 | 138 | • |

* s upínací drážkou dle DIN2201