


Upínač pro nástroje s morse stopkou



DIN 228-1 Form B (DIN 6383)



Název	Kužel	MK	D	A		G 6,3 15.000 min ⁻¹
SK30.50.MK.1.AD	SK30	1	25	50	AD	•
SK30.60.MK.2.AD	SK30	2	32	60	AD	•
SK30.80.MK.3.AD	SK30	3	40	80	AD	•
SK40.50.MK.1.AD	SK40	1	25	50	AD	•
SK40.50.MK.2.AD	SK40	2	32	50	AD	•
SK40.70.MK.3.AD	SK40	3	40	70	AD	•
SK40.95.MK.4.AD	SK40	4	48	95	AD	•
SK40.50.MK.1.ADB	SK40	1	25	50	AD/B	•
SK40.50.MK.2.ADB	SK40	2	32	50	AD/B	•
SK40.70.MK.3.ADB	SK40	3	40	70	AD/B	•
SK40.95.MK.4.ADB	SK40	4	48	95	AD/B	•
SK40.117.MK.2.AD	SK40	2	32	117	AD	•
SK40.133.MK.3.AD	SK40	3	40	133	AD	•
SK40.156.MK.4.AD	SK40	4	48	156	AD	•
SK50.45.MK.1.ADB	SK50	1	25	45	AD/B	•
SK50.60.MK.2.ADB	SK50	2	32	60	AD/B	•
SK50.65.MK.3.ADB	SK50	3	40	65	AD/B	•
SK50.95.MK.4.ADB	SK50	4	48	95	AD/B	•
SK50.105.MK.5.ADB	SK50	5	63	105	AD/B	•
SK50.117.MK.2.AD	SK50	2	32	117	AD	•
SK50.137.MK.3.AD	SK50	3	40	137	AD	•
SK50.167.MK.4.AD	SK50	4	48	167	AD	•
SK50.197.MK.5.AD	SK50	5	63	197	AD	•